

RUSSIAN FEDERATION

MINISTRY OF TRANSPORT OF RUSSIAN FEDERATION

FEDERAL AIR TRANSPORT AGENCY AIRWORTHINESS DIRECTIVE

16 of February, 2022

No. 2022-AHCAT-04

Applicability - ANSAT helicopters (ANSAT, ANSAT-GC models) and their modifications

Designer's State - RUSSIAN FEDERATION

Corrective actions stated in the present Airworthiness Directive are mandatory. None of the operators is allowed to operate the aircraft covered by present Airworthiness Directive otherwise than according to the requirements of present Directive.

In accordance with the conclusions of Conclusion No. 132/239-AHCAT/21 dated 22.12.2021 "Comparative analysis of the development of fatigue cracks of casings of the ANSAT helicopter tail rotor hubs occurred during bench tests" of the Scientific Center of Aircraft Continued Airworthiness of State Research Institute of Civil Aviation the signs of deviations in the treatment of surfaces and holes of the casings of the tail rotor hubs 333.3530.2000, 338.3510.200, 333.3530.2100 in terms of surface reinforcement were revealed. According to the results of periodic fatigue tests in 2020 and 2021 the service life of tail rotor hub of 2000 hours was confirmed.

Based on the Technical decision of JSC "Kazan Helicopters" No. 4/144-2022-KB3 dated 15.02.2022 in order to ensure flight safety and airworthiness of the ANSAT helicopters (ANSAT, ANSAT-GC models), and their modifications the following is

PROPOSED:

- 1. Establish the assigned service life of 2000 hours and assigned service time of 8 years for tail rotor hubs 333.3530.2000, 338.3510.200, 333.3530.2100, being in operation, in accordance with table 1 of Technical decision of JSC "Kazan Helicopters" No. 4/144-2022-KB3 dated 15.02.2022 and for tail rotor hubs produced by JSC "Kazan Helicopters" in 2022.
- 2. Make an entry in section "3. SERVICE AND STORAGE TIME LIMITS" of certificates of tail rotors 333.3510.0000, 333.3510.0000-03, being in operation:

"Assigned service life of tail rotor hub No. (Code) No. (Serial number) - 2000 hours within the limits of assigned service time of 8 years".

- 3. Upon reaching the operating time of the tail rotor assembly 333.3510.0000, 333.3510.0000-03 of 2000 hours, send the tail rotor to JSC "Kazan Helicopters" to carry out the works on investigation and replacement of the tail rotor hubs 333.3530.2000, 338.3510.200, 333.3530.2100.
- 4. Operators of the ANSAT helicopters and their modifications shall inform JSC "Kazan Helicopters" about results of completion of works per p.2 of present Airworthiness directive.
- 5. Airworthiness directive comes into force from the date of its issue and becomes invalid after the issue of service bulletin No. A0481- $59-\Gamma$ by JSC "Kazan Helicopters" or issue of another Airworthiness directive.

Appendix: Technical decision No. 4/144-2022-KB3 dated 15.02.2022, 2 sheets;

Deputy Director General

П. П.

A.A. Novgorodov

Bephonder January 477SI BC

APPROVED BY

Deputy managing director – Head of design JSC "Kazan Helicopters", A.O. Garipov

TECHNICAL DECISION No.4/144-2022-KB3

on continued airworthiness of ANSAT helicopters and their modifications

In accordance with the conclusions of Conclusion No. 132/239-AHCAT/21 dated 22.12.2021 "Comparative analysis of the development of fatigue cracks of casings of the ANSAT helicopter tail rotor hub occurred during bench tests" of the Scientific Center of Aircraft Continued Airworthiness of State Research Institute of Civil Aviation the signs of deviations in the treatment of surfaces and holes of the casings of the tail rotor hubs in terms of surface reinforcement were revealed, while according to the results of periodic fatigue tests in 2020 and 2021, the service life of the tail rotor hub of 2000 hours was confirmed.

In order to ensure the airworthiness of the ANSAT helicopters and their modifications, which are in operation, the following decision was made.

DECISION:

On the ANSAT helicopters (ANSAT, ANSAT-GC models) and their modifications since the release of the Airworthiness directive:

1 Establish service life limitation of 2000 hours for tail rotor hubs 333.3530.2000, 338.3510.200, 333.3530.2100 with serial numbers according to table 1.

Table 1

No.	Serial number of tail	Serial number
INO.		
	rotor	of tail rotor hub
1	Γ20.03.01	2002
2	Γ20.03.02	2003
3	Γ20.08.01	2011
4	Γ20.08.03	2012
5	Γ20.09.02	2014
6	Γ20.10.01	2015
7	Γ20.10.02	2016
8	Γ20.11.02	2018
9	Γ20.11.03	2019
10	Γ20.12.01	2020
11	Γ21.03.01	2102
12	Γ21.03.02	2103
13	Γ21.04.01	2104
14	Γ21.04.03	2101
15	Γ21.05.01	2106
16	Γ21.06.01	2107
17	Γ21.06.02	2102

TECHNICAL DECISION No. 4/144-2022 –KB3 on continued airworthiness of ANSAT helicopters and their modifications

No.	Serial number of tail	Serial number
	rotor	of tail rotor hub
18	Γ21.08.01	2109
19	Γ21.08.02	2110
20	Γ21.09.01	2111
21	Γ21.10.01	2112
22	Γ21.10.02	2113
23	Γ21.11.01	2114
24	Γ21.11.02	2115
25	Γ21.11.03	2116
26	Γ21.11.04	2117
27	Γ21.11.05	2118
28	Γ21.12.01	2119
29	Γ21.12.02	2120
30	Γ21.12.01	2101
31	Γ21.12.03	2121
32	Γ22.01.02	2202
33	Γ21.04.02	2105
34	Γ21.06.03	2108
35	Γ22.01.01	2201

- 2 Tail rotors with serial numbers according to table 1:
- 2.1 Make an entry in section "3. SERVICE AND STORAGE TIME LIMITS" of tail rotor certificate: "Assigned service life of tail rotor hub No. (Code) No. (Serial number) 2000 hours within the limits of assigned service time of 8 years".
- 2.2 Upon reaching the operating time of the tail rotor 333.3510.0000, 333.3510.0000-03 of 2000 hours, send the tail rotor to JSC "Kazan Helicopters" to carry out the works on replacement of the tail rotor hub.
- 3 Inform JSC "Kazan Helicopters" and Federal Air Transport Agency about results of works carried out in accordance with paragraphs 1 and 2.1.
- 4 This technical decision also applies to the tail rotor hubs 333.3530.2000, 338.3510.200, 333.3530.2100 produced by JSC "Kazan Helicopters" in 2022.
- 5 Operators shall follow the requirements of the paragraphs of this technical decision until the issue of service bulletin A0481-БЭ-Γ by JSC "Kazan Helicopters" or issue of another airworthiness directive.