



МИНИСТЕРСТВО ТРАНСПОРТА  
РОССИЙСКОЙ ФЕДЕРАЦИИ  
(МИНТРАНС РОССИИ)

ФЕДЕРАЛЬНОЕ АГЕНТСТВО  
ВОЗДУШНОГО ТРАНСПОРТА

(РОСАВИАЦИЯ)

Ленинградский проспект, 37, Москва  
ГСП-3, 125993, Телетайп 111495  
Тел.: (499)231-53-95 Факс: 231-55-35

e-mail: rusavia@scaa.ru

17.02.2017 № ИСХ-3490/03


На № \_\_\_\_\_ от \_\_\_\_\_

























Руководителям Межрегиональных  
территориальных управлений  
воздушного транспорта Федерального  
агентства воздушного транспорта



Организациям по списку

Управление поддержания летной годности воздушных судов информирует эксплуатантов воздушных судов о выпуске иностранными авиационными администрациями следующих Директив летной годности за период с 01 января по 10 февраля 2017 года:

№	Номер	Выпущено страной	Дата выпуска	Изготовитель ВС	Тип ВС (Классификация ВС, страны выпустившей ДЛГ)	Содержание
1	2017-0023		2017-02-10	AIRBUS	A300-600	Wing - Stringer Joint at Rib 18 - Inspection / Modification
2	US-2017-01-03		2017-02-09	BOEING	717	Standard Practices/Structures - Airworthiness Limitations Section - Amendment
3	2015-0038R1		2017-02-09	AIRBUS	A318, A319, A320, A321	Powerplant - Forward Engine Mount - Inspection
4	US-2017-02-06		2017-02-08	PIPER AIRCRAFT INC.	PA-31P, PA-31T (Cheyenne)	Electrical Power - Main Circuit Breaker Panel Wiring - Inspection
5	2017-0021		2017-02-08	AIRBUS	A330, A340	Fuselage - Cabin and Cargo Compartments Parts - Inspection / Replacement
6	2017-0022		2017-02-08	AIRBUS HELICOPTERS	SA 330 / AS 332 / EC 225	Doors - Cabin Sliding Plug Doors / Emergency Jettisoning System - Inspection
7	US-2017-02-04		2017-02-08	BOEING	747	Nacelles / Pylons - Aluminum Strut Side Skin and Corrosion Resistant Steel Outer Spring Beam Support Fitting - Inspection
8	CF-2016-20R1		2017-02-08	BOMBARDIER	CL-600 (Regional Jet)	Equipment/Furnishings - Electrical Short of Bonding Jumper causing Burnt Water Supply Line and Smoke in Cabin
9	2011-0205R1		2017-02-07	LEONARDO S.p.A. HELICOPTERS	AB139/AW139	[Correction] Stabilizers - Tail Fin Assembly - Inspection / Replacement
10	2017-0020-E		2017-02-07	AIRBUS HELICOPTERS	AS 350 / EC 130, AS 355	Tail Rotor - Pitch Rod - Inspection
11	2017-0018		2017-02-03	SOCATA	TBM 700	Flight Controls - Aileron Control - Modification

12	2017-0019-E		2017-02-03	SAFRAN HELICOPTER ENGINES	ARRIEL 1	Engine Fuel & Control - Drain Valve Assembly - Inspection / Replacement
13	2017-0017		2017-02-01	ROLLS-ROYCE PLC	TRENT 1000	Engine - Intermediate Pressure Compressor Rotor Seal - Inspection
14	2017-0015		2017-01-31	AIRBUS	A380	Fuselage - Belly Fairing - Inspection / Repair / Replacement
15	2017-0016		2017-01-31	328 SUPPORT SERVICES	Dornier 328	Fuel - Fuel Line Clamps - Inspection / Replacement
16	CF-2017-05		2017-01-30	BOMBARDIER	DHC-8	Fuel System - Motive Flow Line Fouling and Motive Flow Line and Pressure Relief Line Broken P-Clamps
17	2017-0014		2017-01-30	ROLLS-ROYCE DEUTSCHLAND	SPEY 506, SPEY 555	Engine - High Pressure Compressor Stage 12 Rotor Discs - Replacement [Life Limit]
18	2015-0141R3		2017-01-30	AIRBUS	A380	Wings - Leading Edge Shear Cleats - Inspection / Replacement
19	2017-0013		2017-01-27	AIRBUS	A380	Wings - Flap Parts - Identification / Inspection [Wrong material]
20	US-2016-25-01		2017-01-27	AVIATION PARTNERS BOEING, BOEING	EASA STC 10016394, STC EASA.IM.A.S.027 23, STC ST01920SE, 747, 757, 767	Auto Flight - On-ground Stabilizer Autotrim Inhibit System - Installation
21	CF-2013-15R2		2017-01-27	BOMBARDIER	DHC-8	Propellers - In-flight Operation of Propeller in Beta Range
22	CF-2017-04		2017-01-26	BOMBARDIER	DHC-8	Fuel System - Corrosion and Wear of Hydraflow Couplings and Sleeves, Fuel Tube End Ferrules, and Fuel Component End Ferrules
23	CF-2017-02		2017-01-26	BELL HELICOPTER TEXTRON CANADA (BHTC)	429	Time Limits & Maintenance Checks - Life- Limited Wheeled Landing Gear Parts Not Serialized
24	CF-2017-03		2017-01-25	BELL HELICOPTER TEXTRON CANADA (BHTC)	427	Stabilizers - Empennage Structure / Cracked Vertical Fin Skins - Inspections
25	2017-0011		2017-01-25	LEONARDO S.p.A. HELICOPTERS	AB139/AW139	Tail Rotor - Tail Rotor Drive Shaft - Inspection / Modification
26	2017-0012		2017-01-25	ROLLS-ROYCE PLC	RB211 TRENT 500	Engine - Low Pressure Compressor Case AFrame Hollow Locating Pins - Replacement
27	US-2016-25-06		2017-01-24	BOEING	DC-9, MD-88	Stabilizers - Horizontal Stabilizer Rear Spar Lower Caps - Inspection
28	2011-0205R1		2017-01-23	LEONARDO S.p.A. HELICOPTERS	AB139/AW139	Stabilizers - Tail Fin Assembly - Inspection / Replacement
29	US-2017-01-02		2017-01-20	BOEING	787	Flight Control Systems - Trailing Edge Flap Rotary Actuator - Inspection / Replacement
30	CF-2017-01		2017-01-20	BOMBARDIER	CL-600 (Challenger)	Navigation - Flight Instruments - Unreliable Air Data in the Cockpit
31	US-2017-01-09		2017-01-18	BOEING	767	Air Conditioning - Flight Deck Display Units - Modification
32	2016-0255R1		2017-01-17	LEONARDO S.p.A. HELICOPTERS	AB139/AW139	Main Rotor Drive - Main Gearbox Input Module - Replacement
33	US-2016-26-04		2017-01-17	ROBINSON HELICOPTER COMPANY	R44 (Raven), R66	Main Rotor - Main Rotor Blades - Inspection

34	2017-0010		2017-01-16	ROLLS-ROYCE DEUTSCHLAND	Tay	Engine - High Pressure Compressor Stage 12 Rotor Disc - Replacement [Life Limit]
35	2017-0009		2017-01-16	AIRBUS	A380	Wings - Flaps Parts - Identification / Inspection [Improper Heat Treatment]
36	2017-0008		2017-01-16	FOKKER SERVICES	F28	Airborne Auxiliary Power - Flexible Fuel Drain Line - Replacement
37	US-2016-26-07		2017-01-16	BOEING	747	Fuselage - Nose Wheel Body Structure - Modification / Inspection
38	US-2017-02-51		2017-01-16	SIKORSKY	S-92	Tail Rotor Control System - Tail Rotor Pitch Change Shaft Assembly Bearing - Removal / Inspections / Replacement
39	US-2016-26-06		2017-01-16	BOEING	787	Wings - Stringer Fittings - Inspections / Replacement
40	2017-0007		2017-01-13	AIRBUS HELICOPTERS	SA 365/366 / AS 365 / EC 155	Tail Rotor - Pitch Control Rod Bearing - Inspection/ Replacement
41	2015-0241R2		2017-01-13	AIRBUS	A350	Flight Controls - Aileron Electro-Hydrostatic Actuator - Inspection / Replacement
42	2016-0016R1		2017-01-12	SAFRAN HELICOPTER ENGINES	MAKILA 2	Engine - Power Turbine Module 04 Bearing Supply Swivel Union - Torque Check
43	US-2016-25-05		2017-01-11	BOEING	747	Stabilizers - Horizontal Stabilizer Upper Skin and Upper Rear Spar Chord - Inspection
44	2016-0249		2017-01-10	AIRBUS	A300-600	Correction] Fuselage - Upper Frame Feet Fittings - Modifications
45	2017-0005		2017-01-10	ZLIN AIRCRAFT A.S.	Z 42 series	Time Limits / Maintenance Checks - Airworthiness Limitations - Implementation
46	2017-0006		2017-01-10	ROLLS-ROYCE PLC	RB211-535	Engine Fuel & Control - Fuel Tube Assemblies - Replacement
47	2017-0003		2017-01-09	ROLLS-ROYCE PLC	RB211 TRENT 700	Engine - Compressor Intermediate Case - Inspection / Repair
48	2017-0004		2017-01-09	EADS CASA	C-295, CN-235	Fuel - Motorised Fuel Valve - Inspection
49	2017-0002		2017-01-09	AIRBUS HELICOPTERS DEUTSCHLAND	EC135/635	Main Rotor Drive - Main Transmission Housing Upper Part - Modification
50	2017-0001		2017-01-06	APPLIANCES	ATA 25 EQUIPMENT / FURNISHINGS	ZODIAC SEATS FRANCE - Cabin Attendant Seats - Inspection
51	US-2016-25-26		2017-01-05	BOEING	MD-90	Navigation - Angle-of-Attack Sensor External Case Heaters - Installation / Wiring Modification / Functional Test
52	US-2016-25-07		2017-01-04	BOEING	767	Fuselage - Aft Pressure Bulkhead - Replacement
53	2016-0238		2017-01-04	AIRBUS	A318, A319, A320, A321	[Correction] Fuselage - Door Stop Fitting Holes at Frames 66/68 - Inspection / Repair
54	2016-0254		2017-01-04	SOLO KLEINMOTOREN GmbH	2625	[Correction] Engine Fuel & Control - Fuel Injection System Control Unit - Modification / Software Update
55	US-2016-24-51		2017-01-03	SIKORSKY	S-92	[Final Rule] Tail Rotor Pitch Change Shaft - Inspection
56	US-2016-25-02		2017-01-03	BOEING	787	[Correction] Flight Control Systems - Markers - Installation
57	US-2016-23-02		2017-01-03	BOEING	777	Nacelles/Pylons - Engine Struts Aft Fairing Lower Web & Heat Shield Castings - Inspection

58	US-2016-25-29		2017-01-03	BOEING	767	Equipment/Furnishings - Cargo Compartment Insulation Blankets - Replacement
59	US-2016-25-21		2017-01-03	BOEING	787	Air Conditioning - Inboard and Outboard Cabin Air Compressor Modules - Replacement

Тексты Директив летной годности находятся на интернет-порталах соответствующих авиационных администраций.

Руководителям Межрегиональных территориальных управлений воздушного транспорта Федерального агентства воздушного транспорта довести данную информацию до подконтрольных авиапредприятий Российской Федерации.

Организациям, эксплуатирующие указанные ВС, принять меры по своевременному выполнению требований применимых директив летной годности.

Начальник Управления  
поддержания летной годности  
воздушных судов



В.В. Кудинов