

№	РАЗРАБОТЧИК	НАИМЕНОВАНИЕ ОБРАЗЦА АТ	Описание	ВЫДАННЫЙ ДОКУМЕНТ	Дата исполнения
1	365 Aerospace DDS Limited	ERJ-170/-190	Change to introduce New Cabin Interior Components (STC 10068513)	FATA-STC030129	26.07.2021
2	365 Aerospace DDS Limited	ERJ-170/-190	Modification to Zodiac Standart Elite Double Seats (STC 10070091)	FATA-STC030170	26.07.2021
3	ACSS	Boeing 767	ADS-B Out modification (ST02126LA)	FATA-STC03065	26.04.2022
4	Aeroconseil	A330	Установка планшета в кабине пилотов (STC 10045473)	FATA-STC03084	20.12.2019
5	Aeroconseil	E190	Установка планшета в кабине пилотов (STC 10055191)	FATA-STC03082	20.12.2019
6	Aeroconseil	A320	personal tablet computer (STC 10044536)	FATA-STC030193	12.03.2021
7	Aeroconseil	A320	TCAS 7.1 Upgrade (STC 10045396)	FATA-STC030188	12.03.2021
8	Aeroconseil	Airbus A330-200	Seat Rails provisions for 9-abreast seat (EASA STC № 10065995)	FATA-STC030252	19.08.2022
9	Aeroconseil	Embraer ERJ 170	Mechanical & electrical installation for personal tablet computer on E170 Family (EASA STC № 10056157)	FATA-STC030270	28.07.2022
10	Aerodata AG	HS125/Hawker	Enhancement of TDR94/94D transponders for ADS-B functionality (STC 10060886)	FATA-STC030123	19.08.2020
11	Aerodata AG	B300	Enhancement of TRD94/94 Transponders for ADS-B functionality (STC 10073170)	FATA-STC030177	28.07.2022
12	Aerolite AG	AW189	EMS Equipment P/N 189-0213100-501:3	FATA-STC03023	02.08.2017
13	AerSale, Inc.	Boeing 737	Installation of an Automatic Dependent Surveillance - Broadcast (ADS-B) Out System (FAA STC № ST04009NY)	FATA-STC030138	26.05.2020
14	Air Ambulance Technology GmbH	EC135 P3/T3	Air Ambulance Equipment P/N 135-25-20-5000-600 and VIP Interior P/N 135-25-20-5000-900	FATA-STC03036-1 FATA-STC03036-2	23.11.2018
15	AirbusHelicopters	AS350 B3	CRASH RESISTANT FUEL SYSTEM ON AS350B3 ARRIEL 2D 27.952	FATA-STC03031	02.04.2018
16	AirbusHelicopters	AS350 B3	CRASH RESISTANT FUEL SYSTEM ON AS350B3 ARRIEL 2D 27.961.C	FATA-STC03032	02.04.2018
17	AirbusHelicopters	EC 130 T2	Установка грузовых контейнеров	FATA-STC03038	05.02.2019
18	AirbusHelicopters	AS350B3	GARMIN G500 GDU 1060L3 ESI-500TA202 USB	FATA-STC030173	31.12.2020
19	AirbusHelicopters	AS350B2/B3EC130B4/T2	INSTALLATION OF L-3 TRILOGY ESI-2000 OR ESI-500 ELECTRONIC STANDBY INDICATOR	FATA-STC030180	31.12.2020
20	Aircraft Engineering & Installation Services, Inc	Boeing 737	Installation of AD Aerospace FlightVu System or AD Aerospace CabinVu 123 System on Boeing 737 (FAA STC № ST02595AT)	FATA-STC03095	19.11.2020
21	ALOFT AeroArchitects	Boeing 737-700	Installation of Provisions for Smoke Detection (FAA STC № ST00405LA-D)	FATA-STC030158	27.07.2021
22	ALOFT AeroArchitects	Boeing 737-700	Installation of Auxiliary Fuel Systems in Boeing 737-700 IGW (BBJ) (FAA STC № ST00936NY)	FATA-STC030157	27.07.2021
23	Alpine Aerotech L.P	Bell 206L/407	Installation of Bear Paw Auxiliary Skid Pads (TCCA STC № SH16-1)	FATA-STC030279	15.05.2023
24	Alpine Aerotech L.P	Bell-505	Bear Paw Auxiliary Skid Pad Installation	FATA-STC030285	15.05.2023
25	AMAC	B737-700	Ka-Band Antenna installation (10060874)	FATA-STC030174	23.10.2020
26	AMTES	Ан-124-100	Уточнение порядка отработки ресурса самолета Ан-124-100	FATA-STC0304	11.12.2017
27	AMTES	Ан-124-100	ADS-B Out v2 Installation	FATA-STC03108	09.12.2019
28	Ancra International	Boeing 747	Installation of Ancra Cargo System (FAA STC № SA5014NM)	FATA-STC030165	19.08.2022
29	Archeion Holdings, L.C.C	AML	Installation of an Avionics, Inc. mini-Quick Access Recorder (mini QAR) model MKI, MKII, or MKIII. or Installation of Avionics, Inc. Quick Access Recorder (QAR) model avRDC or avRDC MAX (FAA STC № ST02472AT)	FATA-STC030195	26.05.2021
30	Archeion Holdings, L.C.C	AML	Installation of an Avionics, Inc. avCM Cellular Module (FAA STC № ST03885AT)	FATA-STC030273	26.04.2022
31	AviaDeCo	B737-700	ADS-B Out (No STC number certification in progress)	FATA-STC030176	19.11.2020

32	Aviation Partners Boeing	Boeing 767-300	Blendet Winglets (ST01920SE)	FATA-STC03052	28.05.2020
33	Avionics Support Group, Inc.	Boeing 777	Installation of an Avionics Support Goup Constatin Friction Mount (cfMount) with an Integrated Power Supply on Boeing B777 Series Aircraft (FAA STC № ST04000AT)	FATA-STC030142	26.05.2021
34	Avionics Support Group, Inc.	AML	Installation of TEAC SD Memory Card Video Reproducer Model № VE-801SDi (FAA STC № ST04432AT)	FATA-STC030143	26.05.2021
35	Avionics Support Group, Inc.	AML	Installation of an Emergency Locator Transmitter (ELT) System (FAA STC № ST03081AT)	FATA-STC030196	26.07.2021
36	Avmax Aviation Services Inc	Bombardier CL-600	Transponder Upgrade for ADS-B Out (TCCA STC № SA15-92)	FATA-STC030145	12.03.2021
37	Avmax Aviation Services Inc	CL-600	Installation of a single or dual Collins Global Positioning System (GPS) GPS-4000A or GPS-4000S Sensor (TCCA STC № SA18-17)	FATA-STC030185	26.07.2021
38	B/E Aerospace	Boeing 777	Installation of the Cobham HGA-7001 High Gain SATCOM Antenna Sub-System (FAA STC № ST03983AT)	FATA-STC03063	12.11.2019
39	B/E Aerospace	Boeing 777	Installation of the Honeywell MCS-7147 SATCOM (FAA STC № ST03980AT)	FATA-STC03064	12.11.2019
40	B/E Aerospace	Boeing 747	Installation of Rockwell Collins ADS-B Out system (FAA STC № ST04446AT)	FATA-STC03062	26.11.2019
41	B/E Aerospace	Boeing 737, 747, 757, 767	Installation of Artex C406-1 Emergency Locator Transmitter (ELT) (FAA STC № ST02929AT)	FATA-STC030105	23.10.2020
42	B/E Aerospace	Airbus A319/A320/A321	Installation of a Kannad Model 406-AF Emergency Locator Transmitter (ELT) (FAA STC № ST02896AT)	FATA-STC030209	28.07.2022
43	B/E Aerospace	Boeing-737-300/ -400/ -500/ -600/ -700/ -800	Installation of an Avtech NA138-714B/C Selective Calling (SELCAL) (FAA STC № ST02967AT)	FATA-STC030268	07.07.2022
44	Bell Helicopter	Bell Helicopter-429	Installation of a Cargo Mirror	FATA-STC0311	05.06.2017
45	Bell Helicopter	BELL 505	Automatic door opener kit	FATA-STC03029	24.12.2019
46	Bell Helicopter	BELL 505	Cowling access door kit	FATA-STC03030	24.12.2019
47	Bell Helicopter	BELL 505	INSTALLATION OF A CARGO MIRROR KIT	FATA-STC03039	24.12.2019
48	Bell Helicopter	BELL 505	INSTALLATION OF FLOOR PROTECTORS	FATA-STC03040	24.12.2019
49	Bell Helicopter	BELL 505	INSTALLATION OF HEADLINER	FATA-STC03066	24.12.2019
50	Bell Helicopter	BELL 505	INSTALLATION OF TINTED WINDOWS	FATA-STC03067	24.12.2019
51	Bell Helicopter	BELL 505	INSTALLATION OF HIGH SKID LANDING GEAR	FATA-STC03068	24.12.2019
52	Bell Helicopter	BELL 505	INSTALLATION OF NIGHTSCANNER	FATA-STC03069	24.12.2019
53	Bell Helicopter	BELL 505	INSTALLATION OF TAIL ROTOR GEARBOX COVER	FATA-STC030161	05.08.2020
54	Bell Helicopter	BELL 505	INSTALLATION OF AN AVIONICS RAIN SHIELD	FATA-STC030162	05.08.2020
55	Boeing	Boeing 737-700	Lower cabin altitude (FAA STC № ST01697SE)	FATA-STC030159	27.07.2021
56	Canard Aerospace Corporation	Boeing 777	Upgrade of Collins GLU-920 MMRs and Collins TPR-901 Mode S Transponders to provide ADS-B Out (FAA STC № ST04184CH)	FATA-STC030104	11.02.2020
57	Carlisle Interconnect Technologies, Inc	Boeing 737	Installation of Honeywell RDR-4000 Weather Radar on Boeing 737 (FAA STC № ST02961CH)	FATA-STC03093	23.10.2020
58	Carlisle Interconnect Technologies, Inc	Boeing 737	Installation of elementary or enhanced surveillance Mode S transponders (FAA STC № ST02162CH)	FATA-STC030220	07.07.2022
59	Carlisle Interconnect Technologies, Inc	Airbus A319/320/321	Installation of ECS EZMount mechanical mounting assemblies on lower frames of cockpit sliding windows (FAA STC № ST02626CH)	FATA-STC030219	28.06.2022
60	Cascade Aviation Services, Inc.	Boeing 737	Installation of a metallic window blanks at cockpit eyebrow windows № 4, and № 5 (FAA STC № ST01630SE)	FATA-STC03086	20.05.2020
61	CMD Flight Solutions LLC	AML	Modification Collins TDR-94/94D transponder for ADS-B Out (STC ST03424CH)	FATA-STC030132	23.03.2020
62	Dart Aerospace	A119/AW119 MKII	SKIDTUBE INSTALLATION	FATA-STC030131	13.05.2020
63	Dart Aerospace	AW119 MKII	CROSSTUBE INSTALLATION	FATA-STC030130	13.05.2020

64	Dart Aerospace	MBB-BK 117 C-2/D2	Emergency Floats with liferafts	FATA-STC 030277	30.06.2021
65	Delta Engineering Corporation	Boeing 777	Installation of a cabin interior on the Boeing 777 300ER series aircraft (FAA STC № ST04072NY)	FATA-STC03077	26.05.2021
66	Delta Engineering Corporation	A330	Installation or removal of a Panasonic Global Communication Suite (GCS) Antenna (FAA STC № ST02884NY)	FATA-STC030229	28.06.2022
67	Eirtech Aviation Services	Boeing 737	737 Family ADS-B Out-Honeywell (STC 10066096)	FATA-STC030126	10.12.2020
68	Eirtech Aviation Services	Boeing 737	Installation of Honeywell ACARS Mark II CMU+ and associated wiring changes (STC 10066845)	FATA-STC030127	04.09.2020
69	Eirtech Aviation Services	B737	Spectralux Dlink (STC 10045472)	FATA-STC030147	09.08.2020
70	Eirtech Aviation Services	A320	Spectralux Dlink (STC 10046455)	FATA-STC030148	19.08.2020
71	Eirtech Aviation Services	B737	Altitude and Take Off Warnings (STC 10040934)	FATA-STC030146	10.12.2020
72	Eirtech Aviation Services	B737	IFE POWER CONTROL (STC 10049196)	FATA-STC030171	10.12.2020
73	FLYHT Aerospace Solutions	Boeing 767-200/300	Automated Flight Information Reporting System	FATA-STC03050	15.07.2022
74	Fokker Services B.V.	Boeing 737	ADS-B Out on Boeing 737NG Series (EASA STC № 10066148)	FATA-STC03076	19.02.2020
75	Fokker Services B.V.	B747	ADS-B Out Installation (STC 10068342)	FATA-STC030109-01	13.05.2020
76	Fokker Services B.V.	Boeing 757	ADS-B Out Installation (STC 10068216)	FATA-STC030118	10.12.2020
77	Fokker Services B.V.	Boeing 767	ADS-B Out Installation (STC 10070805)	FATA-STC030119	10.12.2020
78	Fokker Services B.V.	CL-600	TCAS Upgrade to v. 7.1 (STC 10056201)	FATA-STC030175	27.07.2021
79	Fokker Services B.V.	Boeing 737-300/-400/-500	ADS-B Out on the Boeing 737 classic (EASA STC № 10072602)	FATA-STC030256	28.07.2022
80	FTI Engineering GmbH	King Air 90/200/300 and premier 1/1a	installation ADS-B out (STC 10066166)	FATA-STC030106	24.12.2019
81	FTI Engineering GmbH	EMB-145	ADS-B modification (STC 10067863)	FATA-STC03080	24.12.2019
82	Garmin International, Inc.	AS350	INSTALLATION OF GARMIN G500H Txi DISPLAY SYSTEM, MULTI-FUNCTION DISPLAY	FATA-STC030184	31.12.2020
83	Global AirWorks	Boeing 737	Installation Cockpit Door Surveillance System (FAA STC № ST01443LA)	FATA-STC03061	28.06.2022
84	Global AirWorks	Boeing 767	Installation Cockpit Door Surveillance System (ST01584LA)	FATA-STC03070	28.06.2022
85	Gulfstream Aerospace Corporation	GVII-G500	Installation of an Airplane Interior (FAA STC № ST04310AT-D)	FATA-STC03088	22.10.2021
86	Gulfstream Aerospace Corporation	GV-SP	Validation of 16th STCs (List of STCs see BX-61224)	льных Сертификато	22.10.2021
87	Gulfstream Aerospace Corporation	GV-SP	Installation of an Airplane Interior Multiple STC (FAA STC № ST03686AT-D)	FATA-STC030214	22.10.2021
88	Gulfstream Aerospace Corporation	GIV-X, GV-SP	Installation of Iridium SATCOM System (FANS-1/A+ Over Iridium) (FAA STC № ST04305AT-D)	FATA-STC030215	22.10.2021
89	H4 Aerospace	Boeing 777	ADS-B OUT Upgrade (STC 10067345)	FATA-STC03090	19.02.2020
90	H4 Aerospace	B737	TCAS sys Upgrade (STC 10047524)	FATA-STC030133	26.09.2022
91	Hartzell Propeller Inc	Pilatus Aircraft Ltd. PC-12, PC-12/45, PC-12/4 и PC-12/47E	Installation of Hartzell Propeller model HC-E5A-3A/NC10245B (FAA STC № SA03466CH)	FATA-STC030247	24.11.2021
92	Helicopteres Guimbal	O-360-J2A	Валидация STC на двигатель O-360-J2A	FATA-STC03051	13.07.2020
93	J & C Aero Design and Certification Services EEU LTD	B737	Change interior arrangement (EASA STC 10061828 Rev. 0)	FATA-STC-030197	26.07.2021
94	J & C Aerospace Design and Certification Services EEU Ltd	A320	SURVIVAL ELT INSTALLATION IN CABIN (EASA STC № 10074718)	FATA-STC030248	30.09.2021
95	Jamco America, Inc.	Boeing-777-200/-300	Relocation of VCC cooling system on Boeing Model 777-200 Series and 777-300 Series aircraft (FAA STC № ST02110SE-D)	FATA-STC030264	28.07.2022
96	Jamco America, Inc.	Boeing 777-200	Interior reconfiguration of 777-200 Series airplane (FAA STC № ST01544SE-D)	FATA-STC030275	28.07.2022

97	Jamco America, Inc.	Boeing 777-300ER	Installation of interior reconfiguration on Boeing Model 777-300ER series aircraft (FAA STC № ST02478SE)	FATA-STC030276	28.07.2022
98	Jet Aviation AG	B737	Wireless LAN Activation (STC 10014659)	FATA-STC030190	26.09.2022
99	Kelowna Flightcraft Ltd	Boeing 737-300/-400/-500	B737-300/-400/-500 ADS-B OUT (TCCA STC № SA16-86)	FATA-STC030156	28.06.2022
100	L2 Consulting Services Inc	Boeing 777	Installation of an Iridium Communication System (FAA STC № ST00750DE)	FATA-STC03074	26.05.2020
101	LB Aircraft Engineering LLC	Boeing 737	Installation of a Rockwell Collins CMU-900 ACARS/CPDLC Communication Management Unit (FAA STC № ST04368AT)	FATA-STC030136	26.05.2021
102	Learjet Inc.	BD-700	Installation of software Batch 3.4 to the Honeywell Integrated Avionics Computer (FAA STC № ST01920WI)	FATA-03085	19.08.2022
103	Learjet Inc.	CL-600	Installation of Complete Custom Aircraft Interior (FAA STC № ST01239LA-D)	FATA-STC030235	
104	Learjet Inc.	BD-700	Installation of Honeywell MK V EGPWS Software Upgrade and/or optional Runway Awareness and Advisory System (RAAS) (FAA STC № ST00203BO)	FATA-STC030245	26.09.2022
105	LifePort, LLC	AML	Installation of a Patient Loading and Utility System (PLUS) (FAA STC № SA00096LA)	FATA-STC030222	28.07.2022
106	Lufthansa Technik	Boeing 737 Series	фотолюминесцентная маркировка пола пассажирской кабины (STC 10014281 Rev.1)	FATA-STC-03060	05.02.2020
107	Lufthansa Technik	A330	фотолюминесцентная маркировка пола пассажирской кабины (STC 10014507 Rev.2)	FATA-STC03073	10.12.2020
108	Lufthansa Technik	A320	Installation of non-electrical Floor Path Marking System (STC 10014013)	FATA-STC030124	10.12.2020
109	Lufthansa Technik	Boeing 777	фотолюминесцентная маркировка пола пассажирской кабины (STC 10014897)	FATA-STC03083	26.05.2021
110	Lufthansa Technik	Boeing 767	Installation of non-electrical Floor Path Marking System (STC 10014191)	FATA-STC030125	26.05.2021
111	Lufthansa Technik	Boeing 757-200/-300	Installation of non-electrical Floor Path Marking System (STC 10014713)	FATA-STC030128	12.03.2021
112	Lufthansa Technik	Boeing 737	Zonal Drying System installation (EASA STC № 2004-904)	FATA-STC030246	28.06.2022
113	MAG	AW-139	VIP интерьер	2-1882 FATA approv	27.10.2016
114	MAG	MBB-BK117 D2	Passenger cabin interior VIP customization p/n 6EC10000X002001 (EASA STC № 10055175, revision 1)	FATA-STC030144	27.04.2020
115	MAG	AW-139	VIP интерьер	FATA-STC030168	18.08.2020
116	PMV Engineering	A320	Ice detection (STC 10048286)	FATA-STC030164	10.12.2020
117	PMV Engineering	A320	ELT installation (STC 10062280)	FATA-STC030163	10.12.2020
118	PowerJet S.A.	Sam146	Увеличение ресурса основных деталей ротора КНД двигателя Sam146	FATA-STC03032	28.12.2022
119	Precise Flight Inc	BELL 407	PULSELITE	FATA-STC03096	02.06.2021
120	Rockwell Collins	AML	Collins GPS-4000 GPS-4000A GPS receiver on the Part 25 airplanes listed in the AML (FAA STC № ST01433WI-D)	FATA-STC03047	27.12.2019
121	Rockwell Collins	AML	TCAS II install to Change 7.0 7.1 (FAA STC № ST00907WI-D)	FATA-STC03048	27.12.2019
122	Rockwell Collins	AML	Global Positioning System (GPS) (FAA STC № ST01833WI)	FATA-STC03049	27.12.2019
123	Rockwell Collins	Boeing 737	Installation of GNLU-920 Multi Mode receive in Boeing 737-600/-700/-800 (FAA STC № ST00983LA-D)	FATA-STC03053	27.12.2019
124	Rockwell Collins	AML	TCAS II install to Change 7.0 7.1 for Part 25 aircraft (FAA STC № ST00881WI-D)	FATA-STC03054	07.07.2022
125	Rockwell Collins	Boeing 737	Installation of WXR-2100 MultiScan Weather Radar in Boeing 737-600/-700/-800/-900 (FAA STC № ST01470LA-D)	FATA-STC03055	11.02.2020
126	Rockwell Collins	Boeing 737	Instl TCAS/VHF/RADAR/VOR/DME/ADF/RAD ALT for Boeing 737-700/-800/-900 (FAA STC № ST00748LA-D)	FATA-STC03056	18.05.2020

127	Rockwell Collins	AML	Collins GPS-4000 GPS-4000A GPS receiver on the Part 23 airplanes listed in the AML (FAA STC № SA01434WI-D)	FATA-STC03071	05.02.2020
128	Rockwell Collins	AML	Collins GPS-4000S GPS receiver on the Part 23 airplanes listed in the AML (FAA STC № SA01848WI)	FATA-STC03072	05.02.2020
129	Rockwell Collins	AML	Modification VHF-700B/900B COMM Receiver (FAA STC № ST00526WI-D)	FATA-STC03079	11.02.2020
130	Rockwell Collins	AML	Collins CMU-900 ACARS CORE Software Upgrade (FAA STC № ST01276WI-D)	FATA-STC030110	07.07.2022
131	Rockwell Collins	AML	Modification of a Collins TPR-720, TPR-900 or TPR-901 Mode S Transponder System (FAA STC № ST01256WI-D)	FATA-STC030111	07.07.2022
132	Rockwell Collins	Boeing 767	Installation of ARINC Characteristics 718A for Mode S Transponder Activation (FAA STC № ST01901LA)	FATA-STC030112	06.07.2020
133	Rockwell Collins	Boeing 757	Installation of a Collins TCAS II (FAA STC № ST00138AT)	FATA-STC030113	28.06.2022
134	Rockwell Collins	AML	Modification of an existing FAA approved Collins HF Communication System with HFS-900D Receiver/Transmitter (FAA STC № ST01185WI-D)	FATA-STC030114	20.08.2020
135	Rockwell Collins	AML	Modification of Collins 618M-3/618M-4 VHF COMM Receiver Transmitter (FAA STC № ST00525WI-D)	FATA-STC030115	28.06.2022
136	Rockwell Collins	Boeing 757	Installation of Collins VHF Transceivers (FAA STC № ST01974AT-D)	FATA-STC030116	28.06.2022
137	Rockwell Collins	AML	Modification of an existing FAA approved Collins TPR-720, TPR-900 or TPR-901 Mode S Transponder System (FAA STC № ST01202WI-D)	FATA-STC030117	28.06.2022
138	Rockwell Collins	Boeing 737	Installation of the Head-Up Display Guidance System, Model 4000 (FAA STC № ST00845SE)	FATA-STC030122	28.05.2020
139	Rockwell Collins	Bombardier CL-600	Modification of a Rockwell Collins FMS-4200 System installation to provide WAAS/LPV capability (FAA STC № ST01514WI-D)	FATA-STC030155	28.06.2022
140	Row 44, Inc.	Boeing 737	Installation of Row 44 Broadband Antenna System Provisions (FAA STC № ST02829CH)	FATA-STC030218	07.07.2022
141	Row 44, Inc.	Boeing 737	Installation and activation of a Row 44 Broadband System (FAA STC № ST02836CH-D)	FATA-STC030221	30.01.2023
142	SR Technics Switzerland Ltd	Boeing 777-300ER	Cabin Reconfiguration (EASA approval in progress)	FATA-STC03057	26.05.2021
143	S-TEC	Robinson R44 and R44 II	Автопилот для R44 и R44 II	FATA-STC0306	06.03.2017
144	S-TEC	Airbus Helicopters AS350	Автопилот для AS350B, AS350BA, AS350D, AS350B1, AS350B2, AS350B3, EC130B4, EC130T2	FATA-STC0308	06.03.2017
145	S-TEC	Robinson R66	Автопилот для R66	FATA-STC03010	06.03.2017
146	S-TEC	BELL 505	INSTALLATION OF AN S-TEC HILISAS STABILITY AUGMENTATION SYSTEM / AUTOPILOT	FATA-STC030178	02.04.2021
147	STG Aerospace, Inc.	Boeing 737	Installation of SafTGlo Inc. photoluminescent floor proximity emergency escape path marking system (FPEEPMS) (FAA STC № ST01829AT)	FATA-STC030183	12.03.2021
148	STG Aerospace, Inc.	B737,727,717,777,787,767,757	photoluminescent aisle path marking system (STC 10059799)	FATA-STC030192	26.07.2021
149	STG Aerospace, Inc.	DHC-8	Installation of SAF-T-GLO photoluminescent floor proximity emergency escape path marking system (FPEEPMS) (FAA STC № ST02311AT)	FATA-STC030194	26.07.2021
150	STG Aerospace, Ltd.	Airbus: A300/A310/A319/A320/A321/A330/A340	saf-Tglo Photoluminescent aisle path marking systems Airbus series aircraft (EASA STC № 10058645)	FATA-STC030213	26.05.2021

151	Superjet International	RRJ-95B	Italian Style interiors installation (STC 10045275)	FATA-STC030107	24.04.2020
152	Talon Aerospace, LLC	AML	Installation of a Talon Aerospace LED Replacement General Purpose Lamps (FAA STC № ST04177AT)	FATA-STC030217	30.09.2021
153	TDG Aerospace Inc	B737NG	Установка Universal Fault Interrupter	FATA-STC03046	14.02.2019
154	Teledyne Controls	Boeing 737	Install Teledyne Wireless GroundLink-Quick Access Recorder WGL-QAR (FAA STC № ST01268LA)	FATA-STC03081	07.07.2022
155	Teledyne Controls	Boeing 747	Installation of Teledyne Controls Wireless Ground Link - Quick Access Recorder (FAA STC № ST02172LA)	FATA-STC03098	28.06.2022
156	Teledyne Controls	Boeing 777	Installation of Teledyne Controls Wireless Ground Link - Quick Access Recorder (FAA STC № ST02239LA)	FATA-STC03099	28.06.2022
157	Teledyne Controls	Airbus A320	Installation of Teledyne Controls Wireless Ground Link - Quick Access Recorder (FAA STC № ST01620LA)	FATA-STC030100	28.06.2022
158	TENENCIA	A330	W-IFE (EASA STC № 10060441)	FATA-STC030186	22.10.2021
159	Unical Aero Inc	A330	Installation of AirWorks Cockpit Door Surveillance System (FAA STC № ST01585LA)	FATA-STC030240	07.07.2022
160	VisionSafe Corporation	AML	Installation of Emergency Vision Assurance System (EVAS) (FAA STC № ST00892LA)	FATA-STC03087	20.12.2021
161	VisionSafe Corporation	Boeing 737-800	Installation of Emergency Vision Assurance System (EVAS) (FAA STC № ST00892LA)	FATA-STC03087	28.07.2022
162	VisionSafe Corporation	Boeing 747-400	Installation of Emergency Vision Assurance System (EVAS) (FAA STC № ST00892LA)	FATA-STC03087	28.07.2022
163	VisionSafe Corporation	Gulfstream GV-SP	Installation of Emergency Vision Assurance System (EVAS) (FAA STC № ST00892LA)	FATA-STC03087	20.12.2021
164	VisionSafe Corporation	BD-700	Installation of Emergency Vision Assurance System (EVAS) (FAA STC № ST01057WI)	FATA-STC030233	28.07.2022
165	АО Рычаг	Ансат	Модернизация бортового радиоэлектронного оборудования	FATA-STC03028	22.08.2018
166	АО Рычаг	АНСАТ	МЕДМОДУЛЬ	FATA-ST03058	26.08.2019
167	АО УЗГА	Д-18Т	Авиационный маршевый турбореактивный двигатель Д-18Т серии 3	FATA-STC030265	15.12.2022
168	ООО ИнтерАвиаСервис	Ан-74	Установка радиолокатора "Контур-10Ц" на самолет Ан-74	FATA-STC0307	31.03.2017
169	ПАО Аэрофлот	Embraer ERJ 170-100LR	Альтернативный метод соответствия директиве лётной годности №2022-05-03, выпущенной Уполномоченным органом страны разработчика для ВС типа Embraer ERJ 170	FATA-STC030337	22.11.2023
170	ПАО Ил	Ан-148-100	Увеличение срока службы самолету Ан-148-100 и его модификациям	Fata-STC030320	23.06.2023
171	ПАО ОДК-Сатурн	SaM146	Увеличение ресурса основных деталей ротора КНД двигателя SaM146	FATA-STC03032	28.12.2022
172	ПАО ОДК-Сатурн	SaM146	Введение в номенклатуру двигателя Sam146 альтернативного технического определения свечи зажигания P/N 366-602-405-0	FATA-STC030335	23.11.2023
173	ФГУП ГосНИИ ГА	Ан-28	Уточнение раздела 005 «Ресурсы и сроки службы» Руководства по технической эксплуатации в части увеличения назначенного ресурса с 6000 часов до 9000 часов воздушному винту АВ-24АН самолетов Ан-28, внесенных в Государственный реестр гражданских воздушных судов Российской Федерации»	29.12.2023	29.12.2023
174	ФГУП ГосНИИ ГА	АИ-9В	Увеличение назначенного ресурса до 8000 запусков и 12000 оборотов двигателям АИ-9В за исключением увеличения назначенного ресурса основных деталей (п. 5.15.2 Карты Данных Сертификата типа № СТ 143-ВД)	29.12.2023	29.12.2023